


APPENDIX A

Cultural Resource Survey Forms



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13524
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage


1. NAME OF PROPERTY: Bridge No. 136-A
2. STREET LOCATION: Centerville Road, 1/2 mile north of Barley Mill Road
3. OWNER'S NAME: Delaware Department of Transportation TEL. #:
ADDRESS:
4. TYPE OF RESOURCE(S): building structure X site
object district landscape
5. SURROUNDINGS: (check more than one if necessary)
fallow field cultivated field woodland
scattered buildings X densely built up other
6. FUNCTION: original Bridge present Bridge
7. LIST ADDITIONAL FORMS USED:
CRS-6 (1)
8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates Inc. DATE: 6/1/96
ADDRESS: 100 Halsted Street, East Orange NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13524

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
 - b) Associated traditions or stories
 - c) Noteworthy features
 - d) Comparison with others in area
 - e) Threats
 - f) Additional documentation
- d: similar to bridge No. 136 on Barley Mill Road.
f: additional documentation available in DelDOT bridge inspection files

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization and Early Suburbanization 1880-1940
- b) Historic theme(s) Transportation and Communication

12. EVALUATION Eligible?: Yes() No(X) Potential() Unknown()

- a) Area(s) of significance
- b) NR criteria

13. CERTIFICATION:


Surveyor: [Signature]

Date 6/20/96

PI: [Signature]

Date 6/21/96

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
STRUCTURE FORM

CRS # N-13524
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage

1. ADDRESS OF PROPERTY: Centerville Road, 1/2 mile north of Barley Mill Road
2. TYPE OF STRUCTURE: Bridge
3. DATE OF INITIAL CONSTRUCTION: circa 1935
4. STYLISTIC INFLUENCE:
5. ARCHITECT/BUILDER:
6. INTEGRITY: original site x moved
if moved, when and from where
major alterations and date none
7. CURRENT CONDITION: excellent x good
fair poor
8. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape single barrél arch
height 6-feet
length 23-feet
width 28-feet
 - b) Structural system possibly concrete structure with stone facing
 - c) Foundation
type
material possibly concrete structure faced with stone
 - d) Exterior claddings (modern over original)
walls, parapets stone walls and parapets
roofs

USE BLACK INK ONLY


8. DESCRIPTION (cont'd):

CRS # N-13524

- e) Openings (if applicable)
 - doors
 - windows
 - access
- f) Interior (if applicable)
 - volume
 - linings
- g) Systems (if applicable)
 - heating/ventilating/cooling
 - plumbing
 - electrical
 - lighting

9. ASSOCIATED RESOURCES: _____

10. PLAN SKETCH MAP:



IND

11. SURVEYOR: David C. Berg DATE OF FORM: 6/20/86

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13525
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 2.15

1. NAME OF PROPERTY: Henry B. Thompson House
2. STREET LOCATION: East side of Centerville Road (SR 273) 1/4 mile North of
Barley Mill Road (SR 259).
3. OWNER'S NAME: John Rogers Long TEL. #: _____
ADDRESS: _____
4. TYPE OF RESOURCE(S): building ☒ structure _____ site _____
object _____ district _____ landscape _____
5. SURROUNDINGS: (check more than one if necessary)
fallow field _____ cultivated field _____ woodland _____
scattered buildings ☒ densely built up _____ other _____
6. FUNCTION: original Dwelling present Dwelling
7. LIST ADDITIONAL FORMS USED:
CRS-2; CRS-3 (3)


8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates DATE: 6/1/96
ADDRESS: 100 Halsted Street East Orange, NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13525

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation

c: Large L addition in 1995 has destroyed integrity.
All windows replaced at this time. Previous garage demolished.

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization & Early Suburbanization 1880-1940
- b) Historic theme(s) Architecture

12. EVALUATION Eligible?: Yes() No(X) Potential() Unknown()

- a) Area(s) of significance
- b) NR criteria

13. CERTIFICATION:

Surveyor: [Signature]

Date 6/19/96

PI: [Signature]

Date 6/21/96

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13525
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 2.15

1. ADDRESS OF PROPERTY: East side of Centerville Road (SR 273) 1/4 mile north of Barley Mill Road (SR 259)
2. DATE OF INITIAL CONSTRUCTION: circa 1927
3. FLOOR PLAN/STYLE: Gable-side, 5-bay, Colonial Revival Style
4. ARCHITECT/BUILDER: _____
5. INTEGRITY: original site X moved _____
if moved, when and from where _____
list major alterations and dates (if known) 1995 - Large "L" addition which doubled size of original building.
6. CURRENT CONDITION: excellent X good _____
fair _____ poor _____
7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape "L"
stories 2 1/2
bays 5x2-bay, rectangular (historic) 3x2-bay ell (addition)
wings 2-story, 3-bay wing on east gable; 1 1/2 story 2-bay wing add. to this.
 - b) Structural system Stone original section, frame additions.
 - c) Foundation
materials stone foundation on all sections.
basement full basement
 - d) Exterior walls (modern over original)
materials stucco on all exterior surfaces
color(s) white
 - e) Roof
shape; materials Medium gable; Wood shingles.
cornice Molded cornice
dormers 3 original dormers, each slope of main roof. 2 dormers on wing
chimney location(s) 1 original interior stone chimney on west elevation. 1 - similar chimney on addition gable. 1 interior stone chimney on wing gable.


USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13525

- f) Windows
 spacing Generally regular fenestration, except for south elevation (2 bay-windows)
 type 6/6 sash some 8/8 sash double-hung- all appear new - circa 1995
 trim 4-inch surrounds with molded outer edges, wood sills.
 shutters recessed panel wood, and louvered shutters wood
- g) Door
 spacing south elevation, center
 type recessed panel door
 trim
- h) Porches
 location(s) east elevation gable
 materials wood floor, shed roof, screened-in
 supports stone
 trim
- i) Interior details (if accessible)


8. SKETCH PLAN OF BUILDING:



INDICATE NORTH ON SKETCH

9. SURVEYOR: [Signature] DATE OF FORM: 6/19/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13525
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 2.15

1. ADDRESS OF PROPERTY: East side of Centerville Road (SR 273) 1/4 mile north of Barle Road (SR259) Mi
2. FUNCTION: Garage
3. DATE: circa 1930-1950
4. STYLISTIC FEATURES: rectangular, concrete block with stucco
5. ARCHITECT/BUILDER:
6. DESCRIPTION:
 - a) Structural system Concrete block
 - b) Wall coverings stucco
 - c) Wall openings
windows none
doors two large double door openings on south elevation
other
 - d) Foundation concrete
 - e) Roof
structural system gable-side
coverings asphalt shingle
openings none
 - f) Interiors
floor plan
partition/walls
interior finish
furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:


CRS # N-13525

Show relationship to main building and provide sketch plan of outbuilding.

.....



CA. 1930-1950
Garage



CA. 1995

Garage


↗ pump house



.....

INDICATE NORTH ON SKETCH

8. SURVEYOR:



DATE OF FORM:

6/19/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13525
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 2.15


1. ADDRESS OF PROPERTY: East side of Centerville Road (SR 273) 1/4 mile north of
Barley Mill Road (SR 259)
2. FUNCTION: Pump House
3. DATE: circa 1930-1950
4. STYLISTIC FEATURES: square, concrete block with stucco
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system concrete block
 - b) Wall coverings stucco
 - c) Wall openings
 - windows none
 - doors 1 door, wood with 9-light window
 - other _____
 - d) Foundation concrete
 - e) Roof
 - structural system frame, gable-front
 - coverings asphalt shingles
 - openings _____
 - f) Interiors
 - floor plan _____
 - partition/walls _____
 - interior finish _____
 - furnishings/machinery _____

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13525

Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH

8. SURVEYOR:

[Handwritten signature]

DATE OF FORM:

6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13525
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 2.15

1. ADDRESS OF PROPERTY: East side of Centerville Road (SR 273) 1/4 mile north of
Barley Mill Road (SR 259)
2. FUNCTION: Garage
3. DATE: 1995
4. STYLISTIC FEATURES: Rectangle, concrete block with stucco, 8-inch wide clapboard
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system Concrete block walls to 9 feet, frame walls on 1/2 story
 - b) Wall coverings Stucco on concrete block, 8-inch clapboard (wood) on frame walls
 - c) Wall openings
windows 6/6 double hung wood sashes
doors 1 entrance door, 3 overhead garage doors on west elevation.
other two 1/2 story dormers with 6/6 double-hung windows on west elevation
 - d) Foundation Concrete foundation
 - e) Roof
structural system gable-side corrugated metal roof
coverings corrugated metal
openings two dormers on west slope
 - f) Interiors
floor plan

partition/walls

interior finish


furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13525

Show relationship to main building and provide sketch plan of outbuilding.



.....
INDICATE NORTH ON SKETCH

8. SURVEYOR:

David R. J.

DATE OF FORM:

6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13526
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6

1. NAME OF PROPERTY: Frank G. Tallman House
2. STREET LOCATION: 3800 Centerville Road
3. OWNER'S NAME: Gary and Angela Greenberg TEL. #: _____
ADDRESS: _____
4. TYPE OF RESOURCE(S): building x structure _____ site _____
object _____ district _____ landscape _____
5. SURROUNDINGS: (check more than one if necessary)
fallow field _____ cultivated field _____ woodland _____
scattered buildings x densely built up _____ other _____
6. FUNCTION: original Dwelling present Dwelling
7. LIST ADDITIONAL FORMS USED:
CRS-2 CRS-3 (2)


8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96
ADDRESS: 100 Halsted Street, East Orange, NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13526

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- Relationship to setting
- Associated traditions or stories
- Noteworthy features
- Comparison with others in area
- Threats
- Additional documentation

Intact Colonial Revival Style, not as elaborate as other examples in vicinity such as William A. Worth House.

11. COMPREHENSIVE PLANNING:

- Time period(s) Urbanization and Early Suburbanization 1880-1940
- Historic theme(s) Architecture

12. EVALUATION Eligible?: Yes ☒ No ☐ Potential ☐ Unknown ☐

- Area(s) of significance History, Architecture
- NR criteria Contrib. Resource in Center-Vide Road Historic District - A; C;

13. CERTIFICATION:

Surveyor: David J. Br...

Date 6/29/81

PI: John M. Leach

Date 6/21/81

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13526
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6

1. ADDRESS OF PROPERTY: 3800 Centerville Road
2. DATE OF INITIAL CONSTRUCTION: circa 1939
3. FLOOR PLAN/STYLE: Gable-cross, / Colonial Revival Style
4. ARCHITECT/BUILDER: _____
5. INTEGRITY: original site x moved _____
if moved, when and from where _____
list major alterations and dates (if known) _____
6. CURRENT CONDITION: excellent _____ good x
fair _____ poor _____
7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape Rectangular
stories 2 1/2 story with 1 1/2 story sections
bays 3x2-bay main section with 2x2-bay wings; 2x2-bay garage on N.wing, porch on S
wings 1 1/2 story 2-bay wings on N. and S. gable ends.
 - b) Structural system brick walls with some frame sections.
 - c) Foundation
materials concrete
basement full basement
 - d) Exterior walls (modern over original)
materials brick, 8-inch clapboard on gables and porch.
color(s) white paint
 - e) Roof
shape; materials gabled with slate
cornice boxed cornice
dormers Wings: 2 dormers on W. Elv. Main section: 3 dormers on E. Elv.
chimney location(s) one exterior brick on north elv. gable of main section
one interior brick on the ridge of the south elv. wing.

USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13526

f) Windows

spacing irregular variety, generally in pairs of bays except cross gable.

type 6/6, 12/12, 8/12 double-hung wood

trim 4-inch wood surrounds

shutters 1st-story: paneled wood, 2nd story: louvered wood

g) Door

spacing southernmost bay of main section west elv.

type paneled wood door

trim

h) Porches

location(s) south elevation wing


materials brick floor, shed roof with slate, multi-pane window sashes (fixed)

supports concrete foundation

trim

i) Interior details (if accessible)

8. SKETCH PLAN OF BUILDING:



INDICATE NORTH ON SKETCH

9. SURVEYOR: David C. Berg

DATE OF FORM: 6/20/86

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13526
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6


1. ADDRESS OF PROPERTY: 3800 Centerville Road
2. FUNCTION: Shed
3. DATE: circa 1950
4. STYLISTIC FEATURES: rectangular frame, minimal colonial revival
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system Frame, side-gabled
 - b) Wall coverings vertical wood siding
 - c) Wall openings
 - windows 6-pane fixed wood sash (1)
 - doors wood door built from siding material
 - other _____
 - d) Foundation concrete or concrete slab
 - e) Roof
 - structural system frame, gabled
 - coverings cedar shingles
 - openings none
 - f) Interiors
 - floor plan
 - partition/walls
 - interior finish
 - furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13526

Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH

8. SURVEYOR: David C Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13526
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6

1. ADDRESS OF PROPERTY: 3800 Centerville Road
2. FUNCTION: Garage
3. DATE: circa 1985
4. STYLISTIC FEATURES: rectangular with Colonial Revival Styling, gable-front
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system Brick walls, frame pedimented gable
 - b) Wall coverings Brick with aluminum siding on pedimented gable
 - c) Wall openings
windows 6/6 double-hung on gable pediment, 6/6 double-hung on sides
doors overhead garage door and paneled wood entrance door with 4-pane light.
other
 - d) Foundation concrete
 - e) Roof
structural system frame gabled with pent roof on west gable end
coverings asphalt shingles
openings none
 - f) Interiors
floor plan

partition/walls

interior finish


furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13526

Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH

8. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13527
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6


1. NAME OF PROPERTY: George R. Beach House
2. STREET LOCATION: 3801 Centerville Road
3. OWNER'S NAME: Georgina M. Bissell TEL. #: _____
ADDRESS: _____
4. TYPE OF RESOURCE(S): building ☒ structure _____ site _____
object _____ district _____ landscape _____
5. SURROUNDINGS: (check more than one if necessary)
fallow field _____ cultivated field _____ woodland _____
scattered buildings ☒ densely built up _____ other _____
6. FUNCTION: original Dwelling present Dwelling
7. LIST ADDITIONAL FORMS USED:
CRS-2 CRS-3 (2)

8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96
ADDRESS: 100 Halsted Street, East Orange NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP: CRS # N-13527

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation
- d: unusual French Eclectic Style among a preponderance of Colonial Revival Style dwellings.

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization and Early Suburbanization 1880-1940
- b) Historic theme(s) Architecture

12. EVALUATION Eligible?: Yes ☒ No ☐ Potential ☐ Unknown ☐

- a) Area(s) of significance History, Architecture
- b) NR criteria Contrib. Resource in Centerville Road H.O. A; c

13. CERTIFICATION:

Surveyor: [Signature]

Date 6/20/91

PI: [Signature]

Date 6/21/91

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13527
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6

1. ADDRESS OF PROPERTY: 3801 Centerville Road
2. DATE OF INITIAL CONSTRUCTION: circa 1939
3. FLOOR PLAN/STYLE: Hipped roof, 9-bay principal facade, irregular/ French Eclectic
4. ARCHITECT/BUILDER: _____
5. INTEGRITY: original site X moved _____
if moved, when and from where _____
list major alterations and dates (if known) _____
6. CURRENT CONDITION: excellent _____ good X
fair _____ poor _____
7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape
stories 2 stories
bays 9-bay principal facade-east elevation, asymmetrical plan
wings northernmost single bay is 1-story wing, 2 story win on south elevation
 - b) Structural system brick-load bearing
 - c) Foundation
materials brick
basement full basement
 - d) Exterior walls (modern over original)
materials brick
color(s) spotty whitewash
 - e) Roof
shape; materials hipped roof with asbestos/terra cotta shingles
cornice none
dormers _____
chimney location(s) two interior brick chim neys, one on west slope of main section, the other on east slope of south wing.

USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13527

f) Windows

spacing regular fenestration except for window above main entrance
type full length casemets (French Doors) on 1st Story, 3-pane casements on 2nd
trim
shutters Louvered wood shutters

g) Door


spacing Main entrance off center, 4th bay from north corner.
type louvered wood door, no windows.
trim 4-inch surrounds, louvered shutters

h) Porches

location(s)
materials
supports
trim

i) Interior details (if accessible)

8. SKETCH PLAN OF BUILDING:



9. SURVEYOR: David C. Berg

DATE OF FORM: 6/20/96

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS #	N-13527
SPO Map	8-9-36
Hundred	Christiana
Quad	Wilmington North
Zone	Piedmont
Acreage	6


1. ADDRESS OF PROPERTY: 3801 Centerville Road
2. FUNCTION: Shed
3. DATE: circa 1940
4. STYLISTIC FEATURES: square, concrete block with brick facade, gable-side
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system concrete block
 - b) Wall coverings brick north elevation facade, painted white
 - c) Wall openings
 - windows
 - doors
 - other
 - d) Foundation concrete
 - e) Roof
 - structural system frame
 - coverings asphalt shingles
 - openings none
 - f) Interiors
 - floor plan
 - partition/walls
 - interior finish
 - furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13527


Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH

8. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13527
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 6


1. ADDRESS OF PROPERTY: 3801 Centerville Road
2. FUNCTION: Pool House
3. DATE: circa 1940-1950
4. STYLISTIC FEATURES: _____
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system frame and concrete block
 - b) Wall coverings
 - c) Wall openings
windows
doors
other
 - d) Foundation
 - e) Roof
structural system
coverings
openings
 - f) Interiors
floor plan
partition/walls
interior finish
furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13527

Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH

8. SURVEYOR: David C. Berg DATE OF FORM: 6/20/86

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13528
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 5.86

1. NAME OF PROPERTY: James Rankin Davis House
2. STREET LOCATION: 3900 Centerville Road
3. OWNER'S NAME: Ann Louise McEvoy TEL. #: _____
ADDRESS: _____
4. TYPE OF RESOURCE(S): building X structure _____ site _____
object _____ district _____ landscape _____
5. SURROUNDINGS: (check more than one if necessary)
fallow field _____ cultivated field _____ woodland _____
scattered buildings X densely built up _____ other _____
6. FUNCTION: original Dwelling present Dwelling
7. LIST ADDITIONAL FORMS USED:
CRS-2, CRS-3 (1)


8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96
ADDRESS: 100 Halsted Street, East Orange NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13328

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization and Early Suburbanization 1880-1940
- b) Historic theme(s) Architecture

12. EVALUATION Eligible?: Yes ☒ No ☐ Potential ☐ Unknown ☐

- a) Area(s) of significance History, Architecture
- b) NR criteria Contrib. Resource in Centerville Road H.O. A, C

13. CERTIFICATION:

Surveyor: Paul C. Ryan

Date 6/20/81

PI: Dr. H. Lee

Date 6/21/81

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13528
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 5.86

1. ADDRESS OF PROPERTY: 3900 Centerville Road
2. DATE OF INITIAL CONSTRUCTION: circa 1940-1950
3. FLOOR PLAN/STYLE: Gable-side, 3-bay with wings/Colonial Revival Style
4. ARCHITECT/BUILDER: _____
5. INTEGRITY: original site X moved _____
if moved, when and from where _____
list major alterations and dates (if known) _____
6. CURRENT CONDITION: excellent _____ good X
fair _____ poor _____
7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape rectangular
stories 2-story main block
bays 3-bay (w-w-d)
wings 2-bay south wing (w-w), 1-bay north wing (w), 1-bay garage at north wing
 - b) Structural system ^{wing} stone walls-load bearing, with some frame infill, frame walls at portions of east elevation.
 - c) Foundation materials concrete
basement full
 - d) Exterior walls (modern over original)
materials Principal elevation (west elv) stone, east elv. mostly clapboard
color(s) clapboard painted white, stone-natural
 - e) Roof
shape; materials gabled, frame with cedar shingled roof
cornice boxed
dormers 2- W. elv. south wing. 1-garage N. elv. 1-shed roofed on east elv.
chimney location(s) single stone exterior chimney on south elevation gable


USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13528

- f) Windows
spacing irregular
type 6/12 1st. story, main section 6/6 2nd story others-6/6 and casements.
trim 4-inch surrounds
shutters louvered wood shutters
- g) Door
spacing west elevation, south of center.
type paneled door and 8-pane casement under portico roof
trim
- h) Porches
location(s) south elevation gable
materials frame, wood screens
supports
trim
- i) Interior details (if accessible)

8. SKETCH PLAN OF BUILDING:



INDICATE NORTH ON SKETCH

9. SURVEYOR: David C. Berg

DATE OF FORM: 6/20/96

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13528
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 5.86


1. ADDRESS OF PROPERTY: 3900 Centerville Road
2. FUNCTION: Shed
3. DATE: circa 1940-1950
4. STYLISTIC FEATURES: Gabled-side rectangular, frame
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system frame
 - b) Wall coverings board and batten siding
 - c) Wall openings
 - windows none
 - doors none
 - other two open bays on south elevation.
 - d) Foundation concrete slab
 - e) Roof
 - structural system frame, gabled
 - coverings asphalt shingles
 - openings none
 - f) Interiors
 - floor plan
 - partition/walls
 - interior finish
 - furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13528

Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH


8. SURVEYOR:

David C. Berg

DATE OF FORM:

6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13529
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 14

1. NAME OF PROPERTY: William A. Worth House
2. STREET LOCATION: West side of Centerville Road, at the intersection of Hillside Rd
3. OWNER'S NAME: Intercollegiate Studies Institute TEL. #: _____
ADDRESS: _____
4. TYPE OF RESOURCE(S): building x structure _____ site _____
object _____ district _____ landscape _____
5. SURROUNDINGS: (check more than one if necessary)
fallow field _____ cultivated field _____ woodland _____
scattered buildings x densely built up _____ other _____
6. FUNCTION: original Dwelling present Offices
7. LIST ADDITIONAL FORMS USED:
CRS-2 CRS-3 (3)


8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96
ADDRESS: 100 Halsted Street, East Orange, NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13529

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation

c: Ornate Colonial Revival Style with symmetrical wings
Wide board Oak floors inside, curved staircase
in central hall. High integrity both interior and exterior.

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization & Early Suburbanization
1880-1940
- b) Historic theme(s) Architecture; Major Families,
Individuals, and events

12. EVALUATION Eligible?: Yes ~~XX~~ No() Potential() Unknown()

- a) Area(s) of significance History
Architecture
- b) NR criteria Contributing Resource in
A/C Centerville Road Historic District

13. CERTIFICATION:

Surveyor: [Signature]

Date 6/20/96

PI: [Signature]

Date 6/21/96

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13529
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 14

1. ADDRESS OF PROPERTY: West side of Centerville Road, at the intersection of Hillside Road.
2. DATE OF INITIAL CONSTRUCTION: 1937
3. FLOOR PLAN/STYLE: Gable-side, 5-bay main section with 2-bay wings/Colonial Revival
4. ARCHITECT/BUILDER: _____

5. INTEGRITY: original site ☒ moved _____
if moved, when and from where _____
list major alterations and dates (if known) none

6. CURRENT CONDITION: excellent ☒ good _____
fair _____ poor _____

7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:

- a) Overall shape "U" shape with porches extending north and south of "U"
stories 2 1/2
bays 5-bay
wings two 2-bay wings, one on each gable.
- b) Structural system stone
- c) Foundation
materials stone
basement full basement
- d) Exterior walls (modern over original)
materials stone, uncoursed rubble
color(s) natural stone
- e) Roof
shape; materials gable with rear extensions at wings
cornice Ogee moulded cornice with gable returns
dormers 3 gabled dormers on main section east elev. 1 dormer-each wing.
chimney location(s) Interior brick chimneys at each main gable, and one at each wing gable.

USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13529

f) Windows

spacing regular fenestration: 3 windows per floor, 2 per floor on wings
type triple pane 8/12/12 -1st floor main section, 12/12 2nd flr.wings all 12/12
trim 4-inch surrounds with moulded edges
shutters recessed panel on 1st floor, louvered on 2nd

g) Door

spacing East elevation, center
type 4-foot wide paneled with 20 window panes
trim dentiled flat entablature with fluted pilasters on sides.


h) Porches

location(s) one at each wing gable
materials brick floors, wood, multi-pane fixed windows
supports thin steel posts
trim wrought iron balustrade on flat roof of each porch

i) Interior details (if accessible)

Ornate central curved staircase at rear of central hall.
Original wide board oak floors.

8. SKETCH PLAN OF BUILDING:



INDICATE NORTH ON SKETCH

9. SURVEYOR: David C Berg

DATE OF FORM: 6/20/46

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13529
SPD Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 14

1. ADDRESS OF PROPERTY: West side of Centerville Road, at the intersection of Hillside Road.
2. FUNCTION: Garage (historic) Office (current)
3. DATE: 1937
4. STYLISTIC FEATURES: side gabled, stone, Colonial Revival Style
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system stone walls, uncoursed rubble on 3 sides, frame wall on south eave side.
 - b) Wall coverings natural stone, Horizontal plank siding on south elevation.
 - c) Wall openings
 - windows Two 6/6 windows on east and west elevation gable sides.
 - doors four wood garage door bays and one entrance door on south elevation.
 - other two dormers on south roof slope, 3 on north slope.
 - d) Foundation stone, probably concrete footings
 - e) Roof
 - structural system frame, side gabled, moulded Ogee cornice.
 - coverings asbestos shingles simulating cedar shingles
 - openings 2 dormers on south slope, 3 on north slope all with 6/6 windows
 - f) Interiors
 - floor plan
 - partition/walls
 - interior finish
 - furnishings/machinery

USE BLACK INK ONLY


7. SKETCH PLAN:


CRS # N-13529

Show relationship to main building and provide sketch plan of outbuilding.



 springhouse

 -shed



INDICATE NORTH ON SKETCH

8. SURVEYOR:


David C. Berg

DATE OF FORM:

6/20/96

USE BLACK INK ONLY

CRS-3



CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13529
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 14

1. ADDRESS OF PROPERTY: West side of Centerville Road, at the intersection of Hillside Road
2. FUNCTION: Shed
3. DATE: circa 1940
4. STYLISTIC FEATURES: square plan, concrete block, Colonial Revival Syling
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system concrete block
 - b) Wall coverings stone veneer with stucco painted white to simulate age.
 - c) Wall openings
windows
doors
other
 - d) Foundation concrete with concrete floor
 - e) Roof
structural system frame, gabled with 3-foot overhang on east elevation.
coverings cedar shingles
openings none
 - f) Interiors
floor plan

partition/walls

interior finish

furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13529

Show relationship to main building and provide sketch plan of outbuilding.

Spring
house

Garage

shed

House

↑
N

INDICATE NORTH ON SKETCH

8. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13529
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage

1. ADDRESS OF PROPERTY: West side of Centerville Road, at the intersection of Hillside Road.
2. FUNCTION: Springhouse.
3. DATE: circa 1937
4. STYLISTIC FEATURES: square, stone walls, Colonial Revival Styling.
5. ARCHITECT/BUILDER:
6. DESCRIPTION:
 - a) Structural system stone walls
 - b) Wall coverings natural stone
 - c) Wall openings
 - windows single 4-pane wood awning window on north elevation
 - doors single wood entrance door at south elevation
 - other
 - d) Foundation
 - e) Roof
 - structural system frame, pyramidal
 - coverings asphalt shingles
 - openings louvered cupula at peak.
 - f) Interiors
 - floor plan
 - partition/walls
 - interior finish
 - furnishings/machinery

USE BLACK INK ONLY



7. SKETCH PLAN:

CRS # N-13529

Show relationship to main building and provide sketch plan of outbuilding.



Garage



House



INDICATE NORTH ON SKETCH

8. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13530
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 7.19


1. NAME OF PROPERTY: Deborah B. Halsey Wilson House
2. STREET LOCATION: 4001 Centerville Road
3. OWNER'S NAME: J. Seth and Barbara Cruice TEL. #:
ADDRESS:
4. TYPE OF RESOURCE(S): building x structure site
object district landscape
5. SURROUNDINGS: (check more than one if necessary)
fallow field cultivated field woodland
scattered buildings x densely built up other
6. FUNCTION: original Dwelling present Dwelling
7. LIST ADDITIONAL FORMS USED:
CRS-2 CRS-3 (2)
8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775
ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96
ADDRESS: 100 Halsted Street, East Orange, NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13530

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization & Early Suburbanization 1880-1940
- b) Historic theme(s) Architecture

12. EVALUATION Eligible?: Yes ☒ No ☐ Potential ☐ Unknown ☐

- a) Area(s) of significance ☒ History, Architecture
- b) NR criteria - Contrib. resource in Centerville Road H.C.


13. CERTIFICATION:

Surveyor: [Signature]

Date 6/20/96

PI: [Signature]

Date 6/20/96



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13530
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 7.19

1. ADDRESS OF PROPERTY: 4001 Centerville Road
2. DATE OF INITIAL CONSTRUCTION: 1939
3. FLOOR PLAN/STYLE: Gable-side, 2-bay main block with wings and cross gable garage
4. ARCHITECT/BUILDER: _____
5. INTEGRITY: original site x moved _____
if moved, when and from where _____
list major alterations and dates (if known) _____
6. CURRENT CONDITION: excellent x good _____
fair _____ poor _____
7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape rectangular
stories 2-story
bays East elv: (w-d) West elv. (w-w-w) on main block.
wings North gable wing (w). South gable wings: (w-w), (w-w-w), cross gable
garage at south elevation (w-w). Principal elv. total: 10-bays across.
 - b) Structural system stone. frame wall on principal E. elv. of southern wing.
 - c) Foundation
materials stone
basement full
 - d) Exterior walls (modern over original)
materials stone, cedar shingles on south and west elvs. of garage, S. wing
color(s) natural stone, dark brown cedar shingles.
 - e) Roof
shape; materials gable, side; slate
cornice moulded Ogee cornice
dormers none
chimney location(s) four brick chimneys; one at extreme north gable, one at south
gable of main section, one at south gable of first south wing, one at garage east gable.

USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13530

f) Windows

spacing regular fenestration

type 6/6 double-hung sashes throughout except main block 1st story: 9/6 9/9

trim massive stone lintels with keystones, 4-inch moulded surrounds.

shutters recessed panel shutters

g) Door

spacing north bay of main section, east elevation

type paneled door, fanlight, stone voussoirs over opening, shutters on sides.

trim

h) Porches 2

location(s) west elevation, one porch attached to each main wing.


materials wood frame screens, brick floor, shed roofs

supports brick floor

trim

i) Interior details (if accessible)

8. SKETCH PLAN OF BUILDING:



INDICATE NORTH ON SKETCH

9. SURVEYOR: David C. Berg

DATE OF FORM: 6/20/96

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13530
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 7.19


1. ADDRESS OF PROPERTY: 4001 Centerville Road
2. FUNCTION: Garage (historic) Garage/shed (current)
3. DATE: circa 1940
4. STYLISTIC FEATURES: Gable-front, rectangular, concrete block
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system concrete block
 - b) Wall coverings stucco, unpainted
 - c) Wall openings
windows one 12-pane steel awning window on each eave side.
doors wood overhead garage door on north gable. wood entrance door on W. elv.
other
 - d) Foundation concrete with concrete slab floor
 - e) Roof
structural system frame, pedimented gable.
coverings asphalt shingles
openings none
 - f) Interiors
floor plan rectangular, open
partition/walls none
interior finish exposed framing members
furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13530

Show relationship to main building and provide sketch plan of outbuilding.



INDICATE NORTH ON SKETCH

8. SURVEYOR:

David C. Berg

DATE OF FORM:

6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13530
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 7.19

1. ADDRESS OF PROPERTY: 4001 Centerville Road
2. FUNCTION: Shed (historic) Shed (current)
3. DATE: circa 1950
4. STYLISTIC FEATURES: gable, side, rectangular
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system frame,
 - b) Wall coverings board and batten siding
 - c) Wall openings
 - windows 6-pane fixed window on south elevation (principal facade)
 - doors central wood entrance door on south elevation.
 - other open bay at east corner of south elevation
 - d) Foundation building is set on concret blocks, no other foundation visible.
 - e) Roof
 - structural system frame, side gabled
 - coverings asphalt shingles
 - openings none
 - f) Interiors
 - floor plan
 - partition/walls
 - interior finish
 - furnishings/machinery


USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13530

Show relationship to main building and provide sketch plan of outbuilding.

 Shed



↑
N

 - Garage

INDICATE NORTH ON SKETCH

8. SURVEYOR:

David C. Berg

DATE OF FORM:

6/20/86

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13531
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage

1. NAME OF PROPERTY: Stone Headwall

2. STREET LOCATION: East side of Centerville Road, south of Campbell Road

3. OWNER'S NAME: City of Wilmington TEL. #:

ADDRESS:

4. TYPE OF RESOURCE(S): building x structure site
object district landscape

5. SURROUNDINGS: (check more than one if necessary)

fallow field cultivated field woodland x
scattered buildings densely built up other

6. FUNCTION: original culvert headwall present culvert headwall

7. LIST ADDITIONAL FORMS USED:

CRS-6

8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775

ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96


ADDRESS: 100 Halsted Street, East Orange NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP:

CRS # N-13531

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation

a: headwall built around 1930 during re-alignment of Centerville Road resulting from construction of Hoopes Reservoir. It is similar to stone walls and bridge in Valley Garden Park which is directly east of the headwall.

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization and Early Suburbanization 1880-1940
- b) Historic theme(s) Transportation and Communication

12. EVALUATION Eligible?: Yes ☒ No ☐ Potential ☐ Unknown ☐

- a) Area(s) of significance History Architecture
- b) NR criteria Contrib. Resource in Centerville Road H-D. ~~A~~ Criterion A + C

13. CERTIFICATION:

Surveyor: [Signature]

Date 6/20/96

PI: [Signature]

Date 6/21/96

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
STRUCTURE FORM

CRS # N-13531
SPD Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage

1. ADDRESS OF PROPERTY: East side of Centerville Road, south of Campbell Road
2. TYPE OF STRUCTURE: Bridge/culvert headwall
3. DATE OF INITIAL CONSTRUCTION: circa 1930
4. STYLISTIC INFLUENCE:
5. ARCHITECT/BUILDER:
6. INTEGRITY: original site x moved
if moved, when and from where
major alterations and date
7. CURRENT CONDITION: excellent good x
fair poor
8. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape Barrel arch wall
height 5-feet, 2-foot parapet
length 40-feet
width NA
 - b) Structural system
Probably concrete faced with stone.
 - c) Foundation
type
material
 - d) Exterior claddings (modern over original)
walls, parapets stone on walls and parapet
roofs

USE BLACK INK ONLY


8. DESCRIPTION (cont'd):

CRS # N-13531

- e) Openings (if applicable)
 - doors
 - windows
 - access
- f) Interior (if applicable)
 - volume
 - linings
- g) Systems (if applicable)
 - heating/ventilating/cooling
 - plumbing
 - electrical
 - lighting

9. ASSOCIATED RESOURCES: _____

10. PLAN SKETCH MAP:



INDICATE NORTH ON SKETCH

11. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY

CULTURAL RESOURCE SURVEY
PROPERTY IDENTIFICATION FORM

CRS # N-13532
SPD Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 102.02

1. NAME OF PROPERTY: Valley Garden Park

2. STREET LOCATION: Southeast corner of intersection of Centerville and Campbell Roads

3. OWNER'S NAME: City of Wilmington TEL. #: _____

ADDRESS: _____

4. TYPE OF RESOURCE(S): building ☒ structure ☒ site _____
object _____ district _____ landscape _____

5. SURROUNDINGS: (check more than one if necessary)

fallow field ☒ cultivated field _____ woodland ☒
scattered buildings _____ densely built up _____ other _____

6. FUNCTION: original Park present Park

7. LIST ADDITIONAL FORMS USED:

CRS-2 CRS-3 (1) CRS-6 (3)

8. SURVEYOR: David C. Berg TEL. #: (202) 331-7775


ORGANIZATION: Louis Berger & Associates, Inc. DATE: 6/1/96

ADDRESS: 100 Halsted Street, East Orange, NJ 07019

USE BLACK INK ONLY

9. LOCATION MAP: CRS # N-13532

Please indicate position of resource in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

10. OTHER INFORMATION Consider the following:

- a) Relationship to setting
- b) Associated traditions or stories
- c) Noteworthy features
- d) Comparison with others in area
- e) Threats
- f) Additional documentation

f: documentation in the form of photographs available at the Delaware Historical Society, Wilmington
File: "Hoopes Reservoir/Valley Garden Photograph Collection."

11. COMPREHENSIVE PLANNING:

- a) Time period(s) Urbanization and Early Suburbanization 1880-1940
- b) Historic theme(s) Architecture

12. EVALUATION Eligible?: Yes (X) No () Potential () Unknown ()

- a) Area(s) of significance History Architecture

b) NR criteria Contrib. Resource in A and C Centerville Road Historic District

13. CERTIFICATION:

Surveyor: [Signature]

Date 4/2/94

PI: [Signature]

Date 4/2/94

CRS-1



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
MAIN BUILDING FORM

CRS # N-13532
SPD Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 102.02

1. ADDRESS OF PROPERTY: Southwest corner of intersection of Centerville and Campbell Rds.
2. DATE OF INITIAL CONSTRUCTION: circa 1930-1932
3. FLOOR PLAN/STYLE: Gable-side; 3-Bay with 2-bay wing/ Colonial Revival Style
4. ARCHITECT/BUILDER: _____
5. INTEGRITY: original site X moved _____
if moved, when and from where _____
list major alterations and dates (if known) _____
6. CURRENT CONDITION: excellent _____ good X _____
fair _____ poor _____
7. DESCRIBE THE RESOURCE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape "L"
stories 2 stories
bays 3-bay main section (d-w-w), 2-bay wing at N. gable (w-w) 1-bay ell on wing
wings 2-story, 2-bay wing on north elevation gable.
 - b) Structural system stone
 - c) Foundation
materials stone
basement unknown
 - d) Exterior walls (modern over original)
materials uncoursed stone
color(s) natural stone
 - e) Roof
shape; materials gable, frame with asbestos shingles
cornice moulded Ogee cornice
dormers none
chimney location(s) Three total, two interior at gable ends, one on west elevation
roof slope.

USE BLACK INK ONLY

7. DESCRIPTION (cont'd):

CRS # N-13532

f) Windows

spacing regular fenestration

type 9/9 double hung on main section east elv. 6/9 on wing - both floors

trim 4-inch surrounds

shutters

g) Door

spacing south corner of east elevation

type

trim

h) Porches

location(s)


materials

supports

trim

i) Interior details (if accessible)

8. SKETCH PLAN OF BUILDING:



9. SURVEYOR: David C. Berg

DATE OF FORM: 6/20/86

USE BLACK INK ONLY



CULTURAL RESOURCE SURVEY
RELATED OUTBUILDING FORM

CRS # N-13532
SPC Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 102.02


1. ADDRESS OF PROPERTY: Southwest corner of intersection of Centerville and Campbell Rds
2. FUNCTION: Garage
3. DATE: circa 1930-1932
4. STYLISTIC FEATURES: 2-bay, front gabled/Colonial Revival Style
5. ARCHITECT/BUILDER: _____
6. DESCRIPTION:
 - a) Structural system stone
 - b) Wall coverings stone/pedimented gable with 8-inch wood clapboard
 - c) Wall openings
windows
doors
other
 - d) Foundation
 - e) Roof
structural system gable-frame
coverings asbestos shingles
openings none
 - f) Interiors
floor plan
partition/walls
interior finish
furnishings/machinery

USE BLACK INK ONLY

7. SKETCH PLAN:

CRS # N-13532

Show relationship to main building and provide sketch plan of outbuilding.



8. SURVEYOR:

David C. Berg

DATE OF FORM:

6/20/96

USE BLACK INK ONLY


8. DESCRIPTION (cont'd):

CRS # N-13532

- e) Openings (if applicable)
 - doors
 - windows
 - access
- f) Interior (if applicable)
 - volume
 - linings
- g) Systems (if applicable)
 - heating/ventilating/cooling
 - plumbing
 - electrical
 - lighting


9. ASSOCIATED RESOURCES: Valley Garden Park House, Garage, waterfalls, and footbridge

10. PLAN SKETCH MAP:



11. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
STRUCTURE FORM

CRS # N-13532
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 102.02

1. ADDRESS OF PROPERTY: Southeast corner of intersection of Centerville and Campbell Rds
2. TYPE OF STRUCTURE: Bridge
3. DATE OF INITIAL CONSTRUCTION: circa 1930-1932
4. STYLISTIC INFLUENCE: _____
5. ARCHITECT/BUILDER: Wheelwright & Stevens, Landscape Architects
6. INTEGRITY: original site ☒ moved _____
if moved, when and from where _____
major alterations and date _____
7. CURRENT CONDITION: excellent _____ good ☒
fair _____ poor _____
8. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:
 - a) Overall shape
height
length
width
 - b) Structural system concrete
 - c) Foundation
type
material
 - d) Exterior claddings (modern over original)
walls, parapets stone walls and parapets
roofs

USE BLACK INK ONLY


8. DESCRIPTION (cont'd):

CRS # N-13532

- e) Openings (if applicable)
 - doors
 - windows
 - access
- f) Interior (if applicable)
 - volume
 - linings
- g) Systems (if applicable)
 - heating/ventilating/cooling
 - plumbing
 - electrical
 - lighting


9. ASSOCIATED RESOURCES: Valley Garden Park House, Garage, Waterfalls, and stone walls

10. PLAN SKETCH MAP:



11. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY



DELAWARE STATE HISTORIC PRESERVATION OFFICE
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY
STRUCTURE FORM

CRS # N-13532
SPO Map 8-9-36
Hundred Christiana
Quad Wilmington North
Zone Piedmont
Acreage 102.02

1. ADDRESS OF PROPERTY: Southeast corner of intersection of Centerville and Campbell Rds.
2. TYPE OF STRUCTURE: waterfalls
3. DATE OF INITIAL CONSTRUCTION: circa 1930-1932
4. STYLISTIC INFLUENCE: _____
5. ARCHITECT/BUILDER: Wheelwright and Stevens, Landscape Architects
6. INTEGRITY: original site X moved _____
if moved, when and from where _____
major alterations and date _____
7. CURRENT CONDITION: excellent _____ good _____
fair X poor _____
8. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE: numerous stone walls in stream designed to create small waterfalls in park.
 - a) Overall shape
height 2-feet
length 6-8 feet
width about 2 feet
 - b) Structural system stone
 - c) Foundation
type _____
material _____
 - d) Exterior claddings (modern over original)
walls, parapets _____
roofs _____

USE BLACK INK ONLY


8. DESCRIPTION (cont'd):

CRS # N-13532

- e) Openings (if applicable)
 - doors
 - windows
 - access
- f) Interior (if applicable)
 - volume
 - linings
- g) Systems (if applicable)
 - heating/ventilating/cooling
 - plumbing
 - electrical
 - lighting

9. ASSOCIATED RESOURCES: Valley Garden Park House, Garage, Stone walls, Footbridge

10. PLAN SKETCH MAP:



11. SURVEYOR: David C. Berg DATE OF FORM: 6/20/96

USE BLACK INK ONLY